



<b>Title of Change:</b>	Change to BelaSigna 300 to overcome potential boot issue on small percentage of parts	
<b>Proposed first ship date:</b>	3 August 2015	
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office	
<b>Type of notification:</b>	ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <PCN.Support@onsemi.com>.	
<b>Change category(s):</b>	<input type="checkbox"/> Wafer Fab Change <input type="checkbox"/> Manufacturing Site Change/Addition <input checked="" type="checkbox"/> Product specific change <input type="checkbox"/> Assembly Change <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Test Change <input type="checkbox"/> Material Change <input type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Other: _____	
<b>Sites Affected:</b>	<u>Site 1</u>	<u>Site 2</u>
<input type="checkbox"/> All site(s) <input checked="" type="checkbox"/> not applicable <input type="checkbox"/> ON Semiconductor site(s) : <input type="checkbox"/> External Foundry/Subcon site(s):		
<b>Description and Purpose:</b>		
The VDDC regulator design has been changed in order to avoid an overvoltage on VDDC when powering up VBAT with a voltage above 1.32 V. The VDDC overvoltage could lead to start-up failures of the device		
<b>List of affected Standard Parts:</b>		
B300W35A102XYG		