










<b>Notification Number:</b>	20161115008	<b>Notification Date:</b>	Nov. 18, 2016			
<b>Title:</b>	TPS62110QRSARQ1 – Datasheet update from MSL2 to MSL3					
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services			
<b>Change Type:</b>						
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design			
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet			
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change			
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site			
<input checked="" type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process			
		<input type="checkbox"/>	Wafer Bump Site			
		<input type="checkbox"/>	Wafer Bump Material			
		<input type="checkbox"/>	Wafer Bump Process			
		<input type="checkbox"/>	Wafer Fab Site			
		<input type="checkbox"/>	Wafer Fab Materials			
		<input type="checkbox"/>	Wafer Fab Process			
<b>Notification Details</b>						
<b>Description of Change:</b>						
Texas Instruments Incorporated is announcing an information only notification for TPS62110QRSARQ1 Datasheet update.						
<b>Current: MSL 2</b>						
<b>New: MSL 3</b>						
<b>This is a Datasheet correction only. There is no change to Assembly BOM.</b>						
<b>Reason for Change:</b>						
Update Datasheet with actual MSL qualification testing results (MSL3).						
<b>Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):</b>						
None.						
<b>Changes to product identification resulting from this notification:</b>						
MSL updated to 3 on Labels:						
<b>Example shipping label (not actual product label)</b>						
<table border="1"> <tr> <td>             TEXAS INSTRUMENTS            MADE IN: Malaysia            SOC: 20:  <b>MSL 2 / 260C / 1 YEAR</b> SEAL DT  <b>MSL 1 / 235C / UNLIM</b> 03/29/04            OPT:            ITEM: 39  <b>LBL: 5A (L)T0:1750</b> </td> <td>             G4   </td> <td>           (1P) SN74LS07NSR            (Q) 2000 (D) 0336            (31T) LOT: 3959047MLA            (4W) TKY (1T) 7523483SI2            (P)            (2P) REV: (V) 0033317            (20L) CSO: SHE (21L) CCO:USA            (22L) ASO: MLA (23L) ACO: MYS         </td> </tr> </table>				 TEXAS INSTRUMENTS MADE IN: Malaysia SOC: 20: <b>MSL 2 / 260C / 1 YEAR</b> SEAL DT <b>MSL 1 / 235C / UNLIM</b> 03/29/04 OPT: ITEM: 39 <b>LBL: 5A (L)T0:1750</b>	 G4 	(1P) SN74LS07NSR (Q) 2000 (D) 0336 (31T) LOT: 3959047MLA (4W) TKY (1T) 7523483SI2 (P) (2P) REV: (V) 0033317 (20L) CSO: SHE (21L) CCO:USA (22L) ASO: MLA (23L) ACO: MYS
 TEXAS INSTRUMENTS MADE IN: Malaysia SOC: 20: <b>MSL 2 / 260C / 1 YEAR</b> SEAL DT <b>MSL 1 / 235C / UNLIM</b> 03/29/04 OPT: ITEM: 39 <b>LBL: 5A (L)T0:1750</b>	 G4 	(1P) SN74LS07NSR (Q) 2000 (D) 0336 (31T) LOT: 3959047MLA (4W) TKY (1T) 7523483SI2 (P) (2P) REV: (V) 0033317 (20L) CSO: SHE (21L) CCO:USA (22L) ASO: MLA (23L) ACO: MYS				
<b>Product Affected:</b>						
TPS62110QRSARQ1						

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>