



MT25T Twin-Quad 3V AT 512Mb Datasheet Correction

PCN: 33317

Published: 2019-07-26

Type: Datasheet Change

Description: The 4-Byte 32KB Subsector Erase Command (5Ch) was listed in **Table 20: Command Set** erroneously. The 5Ch command is not supported and it is just a typo. It will be removed from the datasheet.

Reason: Improved Product Quality and Reliability

Product Affected: MT25T 3V AT 512Mb MPNs (QLJS)

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
MT25TL512BBA8E12-0AAT		?
MT25TL512BBA8ESF-0AAT		?
MT25TL512HBA8E12-0AAT		?
MT25TL512HBA8ESF-0AAT		?

*Materials that have been ordered are in **bold**.

Method of Identification: Marketing Part Number- Datasheet has been updated

Micron Sites Affected: Fab 6 - US

Product Ship Date: 2019-06-30

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN