

Discontinuance of Leadis Technology Products

Littelfuse, Inc
 8755 W. Higgins Rd
 Suite 500
 Chicago, IL 60631

To our valued customers,

We would like to notify you of the immediate discontinuance of all Leadis Technology products. All part numbers starting with LDS*** will be discontinued with no replacement due to lack of sales.

Part numbers impacted: See below
Effective date: September 25th, 2019
Replacement products: None
Last time buy: None

LDS8141002-T2	LDS8845002-T2	LDS8869002-T2	LDS8711008-T2
LDS8160002-T2	LDS8846002-T2	LDS8680008-T2	LDS8720008-T2
LDS8161002-T2	LDS8846003-T2	LDS8681008-T2	LDS8724008-T2
LDS9003002-T2	LDS8865002-T2-250/250/250	LDS8640008-T2	LDS8726008-T2
LDS8620002-T2	LDS8866002-T2 300/300/300	LDS8641008-T2	
LDS8621002-T2-960/960	LDS8868002-T2	LDS8710008-T2	

This notification is for your information and acknowledgement. If you have any other questions or concerns, please contact our local Sales team.

We value your business and look forward to assisting you whenever possible.

Sincerely,



Chad Marak
 Vice President, Product Marketing
 Power Semiconductor and IC