



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000971I

DATE: 18-Jun-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	VT1115SFC-001	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1115SFCR-001	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1115SFCX-001	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1526MBFQ-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1526MBFQR-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1626SFQ-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT1626SFQX-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Lead-Free Conversion	VT233WFCR-ADJ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	MAX1786AEUI+CE3	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1115SFCR	VT1115SFCX	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1175MAEVKIT#	N/A	16-Sep-2019	16-Sep-2019	EVKIT is No Longer Supported
Discontinuance	VT1186MFP	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1186MFPR	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1186MFPX	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1526MBFQ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1526MBFQX	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1526MBFQX-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1527MBFQ-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1546MBFQX-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1547MBFQR-008	VT1547MBFQX	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1547MGFQR	VT1547MGFQX	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1556MFQR	VT1556MFQX	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1676SBFQX-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT1677SBFQ-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT232TFCR-ADJ	VT232TFCX-ADJ	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT232WFCR-ADJ	VT232WFCX-ADJ	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 19-Jul-2019

Discontinuance	VT233WFC-ADJ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT267AWFQ-ADJ-008	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT298BFC-ADJ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT298BFCR-ADJ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured
Discontinuance	VT298BFCX-ADJ	N/A	16-Sep-2019	16-Sep-2019	Part can no longer be manufactured