



Product Change Notification - SYST-18QURF217

Date:

29 May 2018

Product Category:

8-bit PIC Microcontrollers

Affected CPNs:**Notification subject:**

Data Sheet - PIC18(L)F27/47K40 28/40/44-Pin, Low-Power High-Performance MCU with XLP

Notification text:

SYST-18QURF217

Microchip has released a new DeviceDoc for the PIC18(L)F27/47K40 28/40/44-Pin, Low-Power High-Performance MCU with XLP of devices. If you are using one of these devices please read the document located at [PIC18\(L\)F27/47K40 28/40/44-Pin, Low-Power High-Performance MCU with XLP](#).

Data Sheet - PIC18(L)F27/47K40 28/40/44-Pin, Low-Power High-Performance MCU with XLP

Notification Status: Final

Description of Change: 1) Fixed errors in the 44-pin TQFP and QFN pin diagrams. 2) Split TMR0 register (18.6.3) into separate 8-bit registers called TMR0H (18.6.3) and TMR0L (18.6.4). 3) Updated Equation 31-1; Correct typo.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 19 Apr 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Revision History:

April 19, 2018: Issued datasheet change notification.

May 29, 2018: Re-issued this PCN to correct the affected CPN list.

Attachment(s):

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.



To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

PIC18F27K40-E/ML
PIC18F27K40-E/SO
PIC18F27K40-E/SP
PIC18F27K40-E/SS
PIC18F27K40-I/ML
PIC18F27K40-I/SO
PIC18F27K40-I/SP
PIC18F27K40-I/SS
PIC18F27K40T-I/ML
PIC18F27K40T-I/MLV02
PIC18F27K40T-I/MLVAO
PIC18F27K40T-I/SO
PIC18F27K40T-I/SS
PIC18F27K40T-I/SSV01
PIC18F47K40-E/ML
PIC18F47K40-E/MV
PIC18F47K40-E/P
PIC18F47K40-E/PT
PIC18F47K40-I/ML
PIC18F47K40-I/MV
PIC18F47K40-I/P
PIC18F47K40-I/PREL
PIC18F47K40-I/PT
PIC18F47K40T-E/ML
PIC18F47K40T-I/ML
PIC18F47K40T-I/MV
PIC18F47K40T-I/PT
PIC18LF27K40-E/ML
PIC18LF27K40-E/SO
PIC18LF27K40-E/SP
PIC18LF27K40-E/SS
PIC18LF27K40-I/ML
PIC18LF27K40-I/SO
PIC18LF27K40-I/SP
PIC18LF27K40-I/SS
PIC18LF27K40T-I/ML
PIC18LF27K40T-I/SO
PIC18LF27K40T-I/SS
PIC18LF47K40-E/ML
PIC18LF47K40-E/MV
PIC18LF47K40-E/P
PIC18LF47K40-E/PT
PIC18LF47K40-I/ML
PIC18LF47K40-I/MV
PIC18LF47K40-I/P
PIC18LF47K40-I/PT
PIC18LF47K40T-E/PTVAO

PIC18LF47K40T-I/ML

PIC18LF47K40T-I/MV

PIC18LF47K40T-I/PT