



Product Discontinuance Notice - PDN 12_0078 Rev. A

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of several AD5384 models

Publication Date: 04-Feb-2013**Last Time Buy Date:** 31-Oct-2012**Last Time Ship Date:** 30-Apr-2013**Reason For Discontinuance**

Based on run rates, limited manufacturing capability and the availability of alternate parts a decision has been made to discontinue the following models: AD5384BBC-3, AD5384BBC-3REEL7, AD5384BBC-5, AD5384BBC-5REEL7, AD5384BBCZ-3.

Rev A: AD5384BBCZ-5 has been removed from the PDN as ADI is continuing to offer this device.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 12_0078 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD5384BBC-3	AD5384	AD5380BSTZ-3	NO	
AD5384BBC-3REEL7	AD5384	AD5380BSTZ-3	NO	
AD5384BBC-5	AD5384	AD5380BSTZ-5	NO	
AD5384BBC-5REEI7	AD5384	AD5380BSTZ-5	NO	
AD5384BBCZ-3	AD5384	AD5380BSTZ-3	NO	

Removed Parts Across All Revisions of PDN 12_0078 Notices

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD5384BBCZ-5	AD5384	AD5380BSTZ-5	No	

Appendix A - PDN 12_0078 Revision History

Rev	Publish Date	Rev Description
Rev. -	15-May-2012	Initial Release
Rev. A	04-Feb-2013	Removal of AD5384BBCZ-5 from the PDN

Analog Devices, Inc. Proprietary Information

DocId:615 Layout Rev:2 Parent DocId:None