



Date July 8, 2020

Doc. No.: 3018011

Masatoshi.Shimajima

General Manager

Small Signal Devices div.

ROHM Co., Ltd.

Product/Process Change Notification

Dear Customer,

This is an announcement of change(s) to the process being used for the products currently supplied.

We request your acknowledgement to receive this notification within the given period.

Please reply by: September 8, 2020

Title of change	Change of production method for UMT3F package (Transistor)		
Affected product(s)	Product name		
	See Below		
Detailed description of change	Now	After	
	Equipment : Old machine (Hoop Line) Mold resin : Halogen contain Marking : 18 dots Factory : ROHM Integrated Systems (Thailand) Co.,Ltd.	Equipment : New machine (Wide Line) Mold resin : Halogen free Marking : 30 dots Factory : ROHM Integrated Systems (Thailand) Co.,Ltd., ROHM Electronics Philippines, Inc.	
Reason for change	Hoop Line was deteriorated, so it was replaced with Wide Line (new machine).		
Anticipated impact on quality	There is no impact on quality level, because our reliability test is passed. And there is no difference with electrical characteristics, because its inner die is no change.		
Identification of change	It is possible to distinguish identification of change by dot marking.		
Planned date of change	ASAP	Sample availale schedule	under mas production
Attachements (data, report)	Yes <input checked="" type="radio"/> No	-	
Comments	If no reply is received by 9/8/2020, ROHM will assume the customers acceptance of this change.		

- PN LIST:
2SA1576UBTLR
2SC4081UBTLR
DTA114EUBTL
DTA114TUBTL
DTA114YUBTL
DTA123JUBTL
DTA124EUBTL
DTA143EUBTL
DTA143TUBTL
DTA143XUBTL
DTA143ZUBTL
DTA144EUBTL
DTC114EUBTL
DTC114TUBTL
DTC114YUBTL
DTC123JUBTL
DTC124EUBTL
DTC143EUBTL
DTC143TUBTL
DTC143XUBTL
DTC143ZUBTL
DTC144EUBTL