

ISSUE DATE	LAST BUY DATE	LAST SHIP DATE	NOTIFICATION No.
9 October 2015	26 February 2016	30 June 2016	PCN-2015-1009-01

This is to advise you that the following products will be discontinued.

PRODUCT ID (DESCRIPTION):

System LSI, Analog IC, and Optoelectronic Devices
(see table on following pages)

DESCRIPTION OF CHANGE:

Sharp is discontinuing the parts shown in the following Table; some have replacements.

EFFECT OF CHANGE:

The following part numbers are discontinued; please see the Table for replacements. There is a Last Buy opportunity available; orders must be placed by the Last Buy date as noted above. The Last Ship date is also noted above.

In case of further questions, please contact your Sharp sales representative.

Affected Part Numbers

PART NUMBER	REPLACEMENT	PART NUMBER	REPLACEMENT	PART NUMBER	REPLACEMENT
LR36688U	NONE	LH163GH2	NONE	LI353305	NONE
LR36689U	NONE	LH163LH2	NONE	LI359337	NONE
LR38522A	NONE	LH163M01	NONE	IR2C91B1	NONE
LZ9FB20A	NONE	LH163PH1	NONE	IR2D08F1	NONE
LZ9FC16A	NONE	LH163RH2	NONE	IR2D17F	NONE
LZ9FC18A	NONE	LH163T01	NONE	IR2D18H	NONE
LZ9FC21A	NONE	LH163T07	NONE	IR2D35W	NONE
LZ9FC23	NONE	LH163UH3	NONE	IR2D37F1	NONE
LZ9FC24	NONE	LH163VH2	NONE	IR2E49U	NONE
LZ9FD15A	NONE	LH164510	NONE	IR2E49U6	NONE
LZ9FD30A	NONE	LH165003	NONE	IR3E11A1	NONE
LZ9FD56	NONE	LH165008	NONE	IR3E11M1	NONE
LZ9FE30	NONE	LH1651H2	NONE	IR3E11P1	NONE
LZ9FF29A	NONE	LH1651H4	NONE	IR3M55U	NONE
LZ9GF14A	NONE	LH1652A3	NONE	IR3M55U6	NONE
LZ9GF29A	NONE	LH1652A4	NONE	IR3M58M4	NONE
LZ9GF32A	NONE	LH165D04	NONE	IR3M58U	NONE
LZ9GF34A	NONE	LH165D05	NONE	IR3M59U	NONE
LZ9GG31A	NONE	LH165FH1	NONE	IR3M59U7	NONE
LZ9GH29A	NONE	LH165FH2	NONE	IR3M61U	NONE
LZ9GH32A	NONE	LH165FH4	NONE	IR3M61U6	NONE
LZ9GJ25A	NONE	LH165NH1	NONE	IR3M63U	NONE
LZ9JG17A	NONE	LH169H4	NONE	IR3M63U6	NONE
QM1H0M0064AS	NONE	LH1669H5	NONE	IR3M64U	NONE
QM1H0M0068AS	NONE	LH1670H1	NONE	IR3M69N4	IR3M97N4
LH153003	NONE	LH168702	NONE	IR3N185	NONE
LH1530F3	NONE	LH168J04	NONE	IR3Y29B1	NONE
LH153902	NONE	LH168RB4	NONE	IR3Y29B3	NONE
LH153EH3	NONE	LH168V04	NONE	LR1R210	NONE
LH154208	NONE	LH168YH4	NONE	LR1R211	NONE
LH154913	NONE	LH169111	NONE	LR1R212	NONE
LH154914	NONE	LH169116	NONE	LR1R213	NONE
LH157422	NONE	LH1691H4	NONE	LR1R214	NONE
LH157L01	NONE	LH169204	NONE	LR1R215	NONE
LH162304	NONE	LH169208	NONE	LR1R216	NONE
LH1624H2	NONE	LH169404	NONE	LR1R217	NONE
LH1624H4	NONE	LH169407	NONE	LR1R218	NONE
LH1624H6	NONE	LH169420	NONE	LR1R219	NONE
LH1627H1	NONE	LH16C1H3	NONE	LR1R220	NONE
LH1627H2	NONE	LH16C1H4	NONE	LR1R221	NONE
LH1627H3	NONE	LH16C2H2	NONE	LR1R222	NONE
LH163A01	NONE	LH16CDH1	NONE	LR1R223	NONE
LH163D07	NONE	LI315601	NONE	LR1R224	NONE
LH163F01	NONE	LI315604	NONE	LR1R225	NONE

Affected Part Numbers, cont'd.

PART NUMBER	REPLACEMENT	PART NUMBER	REPLACEMENT	PART NUMBER	REPLACEMENT
LR1R226	NONE	PQ6CU12X2APQ	NONE	GP1A98HCZ0F	NONE
LR1R227	NONE	PQ6CU12X2APQ	NONE	GP1A98HCZSF	NONE
RB5P0070M2	NONE	PQ7L2020BP	NONE	PC1S3021NTZF	NONE
RB5P0090M	NONE	GA1A1S100WP	NONE	PC1S3052NTZF	NONE
IR3T47G	NONE	GA1A1S202WP	NONE	PC1S3052YTZF	NONE
IR3T47GA	NONE	GA1A1S204WP	NONE	PC1S3052YXPF	NONE
IR3T47GN	NONE	GA1A2S100LY	NONE	PC1S3063NTZF	NONE
PQ012ENB1ZPH	NONE	GA1A2S100SS	NONE	PC1S3063YTZF	NONE
PQ015ENA1ZPH	NONE	PC410L0NIP0F	NONE	PC3SD12NTZAF	PC3SD12NTZA6
PQ015ENA1RPH	NONE	PC410L0NIT0F	NONE	PC3SH11YFZVF	PC3SH13YFZAC
PQ015ENA1ZPH	NONE	PC410L0YIP0F	NONE	PC3SH21YFZVF	PC3SH21YFZAC/KC
PQ015ENAHZPH	NONE	PC410L0YIT0F	NONE	PR33MA11NTZF	PR33MF51NSL6)
PQ015ENB1ZPH	NONE	PC410LENIP0F	NONE	PR33MF51NSLF	PR33MF51NSL6
PQ018ENA1RPH	NONE	PC410LKNIP0F	NONE	PR33MF51NSZF	PR33MF51NSL6
PQ018ENA1ZPH	NONE	PC410LRNIP0F	NONE	PR33MF51YPLF	PR33MF51YPL6
PQ018ENAHZPH	NONE	PC410LRYP0F	NONE	PR36MF51YSLF	PR36MF51YSL6
PQ018ENB1ZPH	NONE	PC410S0NIP0F	NONE	PR39MF51NPLF	PR39MF51NPL6
PQ018ENB1ZPH	NONE	PC410SSNIP0F	NONE	PR39MF51NSLF	PR39MF51NSL6
PQ025ENA1RPH	NONE	PC410SSNIPBF	NONE	PR3BMF51NPLF	PR3BMF51NPL6
PQ025ENA1ZPH	NONE	PC4D10SNIP0F	NONE	PR3BMF51NSDF	PR3BMF51NSD6
PQ025ENAHZPH	NONE	PC4D10SNIPBF	NONE	PR3BMF51NSKF	PR3BMF51NSL6
PQ025ENB1ZPH	NONE	PC4D10SNIPSF	NONE	PR3BMF51NSLF	PR3BMF51NSL6
PQ033ENA1ZPH	NONE	PC4D10SYIP0F	NONE	GP1FAV31TK0F	NONE
PQ033ENAHZPH	NONE	GP1A054RDK0F	NONE	GP1FAV31TKVF	NONE
PQ033ENB1ZPH	NONE	GP1A054RDKLF	NONE	GP1FAV51TK0F	NONE
PQ070XNA1ZPH	NONE	GP1A057RBKLF	NONE	GP1FAV51TKSF	NONE
PQ070XNA2ZPH	NONE	GP1A057SGK0F	NONE	GP1FAV55TK0F	NONE
PQ070XNAHZPH	NONE	GP1A057SGKLF	NONE	GP1FAV55TKSF	NONE
PQ070XNB1ZPH	NONE	GP1A058SCK0F	NONE	GP1FAV55TKVF	NONE
PQ070XNB1ZPH	NONE	GP3A232RCK1F	NONE	GP1FMV31TK0F	NONE
PQ1CX41H2ZPQ	NONE	GP3A233RBK0F	NONE	GP1FMV51TK0F	NONE
PQ1CX53H2MPQ	NONE	GP3A236RCK0F	NONE	GP1FSB31TK0F	NONE
PQ1CX61H1ZPQ	NONE	GP3A239RCK0F	NONE	GP1FSB31TKMF	NONE
PQ1DX095MZPQ	NONE	GP3A240C2K0F	NONE	GP1FSV31TK0F	NONE
PQ1LA125MSPQ	NONE	GP3A241C2K0F	NONE	GP1FSV51TK0F	NONE
PQ1LA155MSPQ	NONE	GP3A242RCK0F	NONE	GP1FSV51TKMF	NONE
PQ1LA185MSPQ	NONE	GP1A70R	NONE	GP1FSV51TKVF	NONE
PQ1LA255MSPQ	NONE	GP3A93RJJ00F	NONE	GP2Y40010K0F	NONE
PQ1LA335MSPQ	NONE	GP1A173LCS0F	GP1A173LCS34	GP2Y40011K0F	NONE
PQ1LA505MSPQ	NONE	GP1A173LCS2F	GP1A173LCS34	GP3Y6003AK0F	NONE
PQ1LAX95MSPQ	NONE	GP1A204HCS0	NONE		
PQ6CB11X1CP	NONE	GP1A273LCS1F	New P/N, Q3 2016		
PQ6CU11X1CPQ	NONE	GP1A98HCPSF	NONE		