

Product Discontinuation



EOL596

■ Last Order Date:	2018-03-31
■ Last Delivery Date:	2018-10-31

Reason: Subcontractor assembly site no longer available

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
IRAM256-1067A2	SP001533504	IRAM256-1067A2	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM236-1067A	SP001533514	IRAM236-1067A	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-1067A	SP001536868	IRAM256-1067A	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-1567A2	SP001538564	IRAM256-1567A2	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-2067A2	SP001539724	IRAM256-2067A2	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-1567A	SP001540208	IRAM256-1567A	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-2067A	SP001547514	IRAM256-2067A	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement
IRAM256-1067A3	SP001591176	IRAM256-1067A3	SIP1A	No Replacement	No Replacement	No Replacement	No Replacement

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!