

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

**Data sheet update affecting products TLE5309D E1211,
TLE5309D E2211 and TLE5309D E5201**

INFORMATION NOTE



N° 066/17

Data sheet update affecting products TLE5309D E1211, TLE5309D E2211 and TLE5309D E5201

► Products affected:

Sales Name	SP N°	OPN	Package
Please refer to 1_cip06617 attached.			

► Detailed Change Information:

Subject: Data sheet update affecting products TLE5309D E1211, TLE5309D E2211 and TLE5309D E5201.

- Reason:**
- Added single ended angle error parameter
 - Document Layout changed
 - Added application circuits

Description:

<u>Old</u>	<u>New</u>
■ Datasheet Rev. 1.0	■ Datasheet Rev 1.1 (for details refer to 4_cip06617 attached).

► Product Identification:

Not applicable; data sheet update introduced only.

► Impact of Change:

No change neither of product nor process.

► Attachments:

Affected products: 1_cip06617
Datasheet Rev. 1.1: 4_cip06617

► Intended start of delivery:

Valid with immediate effect.

If you have any questions, please do not hesitate to contact your local Sales office.

INF N°066/17

Data sheet update affecting products TLE5309D E1211,
TLE5309D E2211 and TLE5309D E5201



Sales Name	SP number	OPN	Package
TLE5309D E1211	SP001227880	TLE5309DE1211XUMA1	PG-TDSO-16-2
TLE5309D E2211	SP001227888	TLE5309DE2211XUMA1	PG-TDSO-16-2
TLE5309D E5201	SP001227884	TLE5309DE5201XUMA1	PG-TDSO-16-2